


Australian Wool Testing Authority Ltd - trading as AWTA Product Testing A.B.N 43 006 014 106

1st Floor, 191 Racecourse Road, Flemington, Victoria 3031 P.O Box 240, North Melbourne, Victoria 3051 Phone (03) 9371 2400 Fax (03) 9371 2499

TEST REPORT

37-39	n Image Pty Ltd Chard Road /ale NSW 2100	Test Number Issue Date Print Date	: 19-00680 : 22/11/201 : 22/11/201	19			
Sample Descripti	on Clients Ref : "Focus Quilted" Woven quilted fabric with foam fill Colour : Grey End Use : Upholstery, Wrapped Panels, Oper Nominal Composition : 100% Polyester and						
N 1021-1-2006	Furniture - Assessment of the Ignitability of U Source - Smouldering Cigarette	Furniture - Assessment of the Ignitability of Upholstered Furniture Part 1: Ignition Source - Smouldering Cigarette					
	Date of Testing		21/11/2019				
	Did Ignition Occur		No				
	Extent of Damage	Vertical	Horizontal				
	Extent of Damage Length	Vertical 4	Horizontal 2	mm			
	-			mm mm			
	Length	4	2				
	Length Width	4	2 4	mm			
	Length Width Depth	4	2 4 6	mm mm			
	Length Width Depth Ignition Source Time	4	2 4 6 7.25	mm mm min			
	Length Width Depth Ignition Source Time Flame Time	4	2 4 6 7.25 0.0	mm mm min min			

The above test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials or products in use.



APPROVED SIGNATORY

MANAGING DIRECTOR

В



Australian Wool Testing Authority Ltd - trading as AWTA Product Testing A.B.N 43 006 014 106

1st Floor, 191 Racecourse Road, Flemington, Victoria 3031 P.O Box 240, North Melbourne, Victoria 3051 Phone (03) 9371 2400 Fax (03) 9371 2499

TEST REPORT

Client :	Woven Image Pty Ltd	Test Number	:	19-006803
	37-39 Chard Road	Issue Date	:	22/11/2019
	Brookvale NSW 2100	Print Date	:	22/11/2019


BSEN 1021.2-2006 (Modified)

Furniture - Assessment of the Ignitability of Upholstered Furniture Part 2: Ignition Source - Match Flame Equivalent

Date of Testing		21/11/2019	
Did Flaming Ignition Occur?		Yes	
Did Smouldering Ignition Occur?		No	
Extent of Damage	Vertical	Horizontal	
Length	450	150	mm
Width	310	320	mm
Depth	75	75	mm
Time for Burning to reach Rig Extremities		4.50	min
Test Assembly Self Extinguished	No		
Assembly Smouldering when Dismantled		No	

The above test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials or products in use.

Modification: Propane/Butane mixture used as ignition source.



MANAGING DIRECTOR