CSIRO ACOUSTIC MEASUREMENT REPORT CSIRO

Commonwealth Scientific and Industrial Research Organisation, Infrastructure Technologies Acoustics Testing Laboratory, Gate 5, 2 Normanby Road, Clayton, Vic 3168 Australia

Client: Woven Image Pty. Ltd.

37-39 Chard Road, Brookvale, NSW 2766 Australia

Measurement Type: Sound Absorption

AS ISO 354–2006 "Acoustics–Measurement of sound absorption in a reverberation room" AS ISO 11654–2002 (ISO 11654:1997) "Acoustics-Rating of sound absorption-Materials and systems"

Test Specimen [Specimen area: 3.6 x 3.0 m (10.8 m²)]

Name: Woven Image 'EchoPanel® Element' Ceiling Absorber - installed on 200 mm spacers; absorption coefficients calculated based on one absorber per 10.8 m² of ceiling area - see diagram (below right).

Test Specimen Details:1

- 'EchoPanel® Element' specimen composition:
- 'EchoPanel® Element' blades: composed of Woven Image EchoPanel® 100% polymer fibre (PET, 60% recycled), 24 mm thick ± 7%, area density: 3000 gsm; individual blade dimensions: 2350 x 215 x 24 mm (slightly trapezoidal in shape, with two rounded corners); each blade was made with four half-depth slots cut
- from one or other long edge to enable them to be assembled together into a grid formation in accordance with manufacturer's instructions; the assembled object forming a single unit. Woven Image Ceiling/Wall Clips (see adjacent illustration): proprietary plastic (ABS) clips
- designed to grip a 24 m thick 'EchoPanel® Element' blade and clip to a standard ceiling Tee above, with a swivelling connection between the two.
- Supplied for testing unassembled as a standard 'EchoPanel® Element' kit with contents: 8 x pre-cut blades (4 of each slotting variant), 16 x ceiling/wall clips and an installation guide (version updated subsequent to test):
- 24 MM SUSPENSION KIT_Installation Guide_26-03-2019.pdf

Installation:

- The reverberation chamber was swept and vacuumed prior to testing to remove dust and debris.
- Due to test-laboratory constraints, this product was tested upside-down, resting on 200 mm timber spacers (installed to ceiling side of test specimen) on the floor of the test chamber in a manner acoustically equivalent to being suspended below the ceiling of a normal room.
- The test specimen was placed directly on the concrete floor of the test chamber not parallel with the walls of the chamber (12° angle), with no enclosure surrounding the test specimen.
- The test specimen was assembled as per manufacturer's instructions. No ceiling grid was used in the installation of the specimen for testing
- · Specimen assembly and installation was carried out by laboratory staff.

Measurement Details & Results



Legal Information and Disclaimer Copyright © 2019 CSIRO. To the extent permitted by law, CSIRO (including its employees and consultants) excludes all liability to any person for any consequences, including but not limited to all losses, damages, costs, expenses and any other compensation, arising directly or indirectly from using any information or material contained in this document. Results relate only to items tested. No alterations permitted. This report may be distributed only in its entirety. Page 1 of 1

AC253-03-1

Specimen as tested (image flipped upside down)

3.6m

Diagram of treatment of area occupied by test specimen

3.0m

Report No: